Attorney Docket No. 1466.1039



## N THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Takashi SHIIZAKI, et al.

Application No.: 09/885,001

385,001 ATTENTION

Confirmation No.: 3545

**CERTIFICATE OF CORRECTION** 

Filed: June 21, 2001

**BRANCH** 

U.S. Patent No.: 7,116,288

Issued: October 3, 2006

For: DRIV

DRIVING METHOD OF PLASMA DISPLAY PANEL AND DISPLAY DEVICE

## REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date

Dec. 19, 2006

By:

H. J. Stafas

Registration No. 22,010

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500

Facsimile: (202) 434-1501

Certificate

DEC 2 1 2006

of Correction

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 7,116,288

DATED: October 3, 2006

INVENTOR(S): Takashi SHIIZAKI, et al.

First page, Column 2 (Abstract), Line 1, after "having" delete "a".

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP

1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 7,116,288

No. of add'l copies @ 50¢ per page